Scope of Work Completed

Property Address: <u>3031 Cesery Blvd.</u>

| Completed | |
|--------------|---|
| $\sqrt{}$ | Install new roof |
| \checkmark | Install 75 feet on new plumbing to main water |
| \checkmark | Re-finish wood floors |
| $\sqrt{}$ | Repair ceiling in master bedroom |
| \checkmark | Repair ceiling in hallway bathroom |
| \checkmark | New knock down ceiling in master bedroom |
| \checkmark | New knock down ceiling in hallway bathroom |
| \checkmark | Install trim throughout house |
| $\sqrt{}$ | Install base boards throughout house |
| \checkmark | Paint interior of home, two tone walls 1/2 bone with white trim |
| \checkmark | Prime all wood trim |
| $\sqrt{}$ | Paint exterior of home |
| \checkmark | Re-finish kitchen cabinets |
| $\sqrt{}$ | Epoxy kitchen counter top |
| \checkmark | Cut counter top to fit cabinet |
| \checkmark | Tree removal |
| $\sqrt{}$ | Frame and finish closet |
| \checkmark | Install door acces to water heater |
| \checkmark | Insulate walls |
| \checkmark | Level floor in 4th bedroom |
| \checkmark | Install smoke detectors |
| $\sqrt{}$ | Install hardware for ca all cabinets |
| \checkmark | Repair doors in two bedrooms |
| \checkmark | Repair sub floor in laundry room |
| $\sqrt{}$ | Install new vanity |
| \checkmark | Install new faucet and plumbing |
| \checkmark | Remove broken window on back of house |
| \checkmark | Replace broken window and missing window on back of house |
| $\sqrt{}$ | Install new refridgerator |
| $\sqrt{}$ | Install closet rod for walk in closet |
| $\sqrt{}$ | Install toilet paper holder |
| $\sqrt{}$ | Remove old locks and dead bolts on front and back doors |
| \checkmark | Install new locks and dead bolts on front and back doors |
| \checkmark | Remove broken window cranks |
| \checkmark | Install new window cranks |
| $\sqrt{}$ | Install blinds throughout house |
| $\sqrt{}$ | Install new ceiling fans in 4 rooms |
| \checkmark | Install new lighting |